



Speedy Asset Services Limited



Report of Thorough Examination of Lifting Equipment

In accordance with the Lifting Operations and Lifting Equipment Regulations 1998

Report Number: 2971/4A3/14

LOCATION DETAILS

Name & Address of Equipment Owner	Location of Thorough Examination	Site Destination
DAYTONA STAGE HIRE CROSS PIPES HOUSE, PENISTONE ROAD, HUDDERSFIELD, HD8 8XW		

ITEM DETAILS

EXAMINATION DETAILS

ID Number	DS40	Asset No.		State: Examination Type (Exceptional, Thorough, Scheme)	Thorough	
SWL	N/A	Proof Load			Is the equipment safe to operate?	Yes without restrictions
Radius		Span				Details of any defects or limitations of use and necessary repairs
Description	TRAILER MOUNTED STAGING UNIT			Date by which defects must be remedied	N/A	
Notes						

Examination Schedule (Months)	6	12	<input checked="" type="checkbox"/>	Other		Latest date for next examination	29/09/2012	Witness Name	
First Examination after installation?	No	Installed Correctly?		N/A		Date of last examination	10/08/2010	Authority	
Date of this Examination?	29/09/2011	Date of Manufacture?				Date of this report	10/10/2011	Signature	
Are any defects reportable to the relevant Enforcing Authority?				No					

This equipment was manufactured in accordance with the Machinery Directive.

Authenticating Signature:

Examiner's Name:

R McCourt

Authenticator's Name:

R McCourt

Lifting Equipment Inspector for Speedy Asset Services Limited