



Report of a Thorough Examination of Lifting and/or Work Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 (Schedule 1.7) S.I. 2307 and the Provision & Use of Work Equipment Regulations 1998 S.I. 2306; or Lifting Operations and Lifting Equipment Regulations (Northern Ireland) 1999 - as amended and The Provision and Use of Work Equipment Regulations (Northern Ireland) 1999 or Safety, Health and Welfare at Work (General Application) Regulations 2007 - as amended and the Working at Height Regulations 2005



Date of Thorough Examination	18/06/2019	Date of Report	18/06/2019	Job Number	PRJ-028182/138122	Report Number	02378377
Name and Address of employer for whom the thorough examination was made: DAYTONA EXHIBITIONS PO BOX 43 HUDDERSFIELD WEST YORKSHIRE HD8 8XW ID tag used (if applicable):				Address at premises where the examination was made: B&B TRUCKS HIGHAM LANE DODWORTH BARNSELY SOUTH YORKSHIRE S75 3LA S75 3LA Site Ref: Site Grid Ref: Location Name (if any): N/A			
Description and Identification of the Equipment:				Safe Working Load(s)	Date of Manufacture	Date of Last Thorough Examination	
Asset Number DS60 Serial No DS60 Asset Description MISC MINI PLANT TRAILER MOUNTED STAGING UNIT				N/A	N/A	20/06/2018	
				Inspection Frequency		12 Months	
Is this the first examination after installation or after assembly at a new site or location?		No		Was the examination carried out in accordance with an examination scheme?			
If answer to above is Yes, has equipment been installed correctly?		Yes		Was the examination carried out after the occurrence of exceptional circumstances?		No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:				N/A			
Is the above a defect which is of immediate danger to persons?						No	
Is the above a defect which is not yet but could become a danger to persons?						NA	
If the answer to the above is Yes, state the date by which the defect could become a danger						N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				NONE			
Particulars of any tests carried out as part of the examination.				A THOROUGH EXAMINATION WAS CARRIED OUT			
Inspection Notes or Observations							
Is this equipment safe to operate?						Yes	
Name and qualifications of the person making this report: wynn.kimberley Company Approved and Qualified Examiner			Name (and signature) of the person authenticating this report: wynn.kimberley			Latest date by which next thorough examination must be carried out:	
						18/06/2020	

Thorough Exam 2

Name and Address of employer of persons making and authenticating this report:

Lloyds British, a trading division of Speedy Asset Services Ltd, Kings Hill Business Park, Darlaston Road, Wednesbury, West Midlands, WS10 7SH.

A test certificate or EC Declaration of Conformity for the equipment should be held on file. The latest date by which the next examination should be completed (as specified above) is subject to the equipment being properly used and maintained. For this purpose, maintained means such maintenance as is reasonable to expect the owner/user to ensure is carried out independently of any advice from the competent person making the examination. Copyright 2017 Speedy Asset Services Ltd. All rights reserved.

Lloyds British is a trading division of Speedy Asset Services Ltd. Registered office: Speedy Asset Services Ltd, Chase House, 16 The Parks, Newton-le-Willows, Merseyside, WA12 0JQ.

Registered in England and Wales under 6847930. VAT Reg No GB 151 6295 70